

MISSOURI MISSOURI MISSOURI-KANSAS CITY BASIN AD A105337

WELLINGTON - NAPOLEON WATERSHED STRUCTURE C-21
LAFAYETTE COUNTY, MISSOURI


MO 10284



PHASE 1 INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM

OTIC FILE COPY





PREPARED BY: HOSKINS-WESTERN-SONDEREGGER, INC.

FOR: STATE OF MISSOURI

SEPTEMBER, 1978

81 10 8 043

UNCLASSIFIED
SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

REPORT DOCUMENTATION PAGE	READ INSTRUCTIONS BEFORE COMPLETING FORM		
1. REPORT NUMBER 2. GOVT ACCESSION NO.	3. RECIPIENT'S CATALOG NUMBER		
AD-A10533	7		
A. TITLE (and Subtitle) Phase I Dam Inspection Report National Dam Safety Program	S. TYPE OF REPORT & PERIOD COVERED Final Report		
Wellington-Napoleon Wtrshd Structure C-21 Lafayette County, Missouri (MO 10284)	6. PERFORMING ORG. REPORT NUMBER		
7. Author(*) Hoskins-Western-Sonderegger, Inc.	8. CONTRACT OR GRANT NUMBER(*)		
9. PERFORMING ORGANIZATION NAME AND ADDRESS	DACW43-78-C-0155 10. PROGRAM ELEMENT, PROJECT, TASK AREA & WORK UNIT NUMBERS		
U.S. Army Engineer District, St. Louis	AREA & WORK UNIT NUMBERS		
Dam Inventory and Inspection Section, LMSED-PD			
210 Tucker Blvd., North, St. Louis, Mo. 63101			
U.S. Army Engineer District, St. Louis	September 78		
Dam Inventory and Inspection Section, LMSED-PD 210 Tucker Blvd., North, St. Louis, Mo. 63101	13. NUMBER OF PAGES Approximately 80		
14. MONITORING AGENCY NAME & ADDRESS(If different from Controlling Office)	15. SECURITY CLASS. (of this report)		
	UNCLASSIFIED		
Cillary P/Hacker	15a. DECLASSIFICATION/DOWNGRADING SCHEDULE		
IS DISTRIBUTION STATEMENT (of this Pringet)			
Approved for release; distribution unlimited.	12 93		
National Dam Safety Program.	€00 • • • • • • • • • • • • • • • • • • •		
Wollington - Nanoleon Watershed			
Structure G-21 (MO 10284), Missou	ri (dri)		
A Kansas City Basin, Lafayette Goung	cy, i		
Missouri. Phase I Inspectrion Repo	rt.		
1			
18. SUPPLEMENTARY NOTES	í		
	ļ		
	1		
19. KEY WORDS (Continue on reverse side if necessary and identify by block number)			
Dam Safety, Lake, Dam Inspection, Private Dams			
20. ABSTRACT (Continue on reverse side H necessary and identify by block number)			
This report was prepared under the National Program of Inspection of Non-Federal Dams. This report assesses the general condition of the dam with respect to safety, based on available data and on visual inspection, to			
determine if the dam poses hazards to human life or property.			
	ļ		
	(

UNCLASSIFIED

SECURITY CLASSIFICATION OF THIS PAGE (When Data Entered)

ECURITY CLASSIFICATION OF THIS PAGE(When Date Entered)	
- · ·	
	j
	1
	1
	1
	- 1
	j
	ł
	ł
	İ
	- 1
	- 1
	- 1
	1
	- 1
	}
	1
	- 1
	}
	ł
	1
	- {
	}
	- }
	i
	ĺ
	1
	1
	i
	- }
	1
	- 1
	ì
	Í
	İ
	1
	- 1
	- 1

1

(<u>Ş</u>



DEPARTMENT OF THE ARMY ST. LOUIS DISTRICT, CORPS OF ENGINEERS 210 NORTH 12TH STREET ST. LOUIS, MISSOURI 63101

SUBJECT: Wellington-Napoleon Watershed Structure C-21 Dam (Mo. 10284) Phase I Inspection Report


This report presents the results of field inspection and evaluation of the Wellington-Napoleon Watershed Structure C-21 Dam:

It was prepared under the National Program of Inspection of Non-Federal Dams.

This dam has been classified as unsafe, non-emergency by the St. Louis District as a result of the application of the following criteria:

- 1) Spillway will not pass 50 percent of the Probable Maximum Flood.
 - 2) Overtopping could result in dam failure.
- 3) Dam failure significantly increases the hazard to loss of life downstream.

SUBMITTED BY:	Chief, Engineering Division	12 App 1039
APPROVED BY:	Colonel, CE, District Engineer	13 APR 1979 Date



Approved for public release;
Distribution Unlimited

PHASE I REPORT

NATIONAL DAM SAFETY PROGRAM

Name of Dam State Located County Located Stream Date of Wellington-Napoleon Watershed Structure C-21 Missouri Lafayette County Tributary to Missouri River September 15, 1978

Inspection

Wellington-Napoleon Watershed Structure C-21 was inspected by an interdisciplinary team of engineers. from Hoskins-Western-Sondereggers Ins. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.

The guidelines used in the assessment were furnished by the Department of the Army, Office of the Chief of Engineers and developed with the help of several Federal and State agencies, professional engineering organizations, and private engineers. Based on these guidelines, this dam is classified as a small size dam with a high downstream hazard potential. Failure would threaten life and property. The estimated damage zone extends one mile downstream of the dam. Within the first one-half mile downstream of the dam are four to five houses, a Missouri-Pacific railroad crossing and a Highway 24 crossing.


Our inspection and evaluation indicates that the spillways do not meet the criteria set forth in the guidelines for a dam having the above size and hazard potential. Because of the number of houses and the railroad and highway crossings within the first one-half mile downstream of the dam the spillways should be capable of passing the probable maximum flood without overtopping the dam and possibly causing failure of the dam. The spillways will pass a 100-year flood (flood having a one percent chance of being exceeded in any one year) without overtopping the dam. The spillways will also pass 40% of the Probable Maximum Flood without overtopping the dam. The Probable Maximum Flood (PMF) is defined as the flood that may be expected from the most severe combination of critical meteorologic and hydrologic conditions that are reasonably possible in the region.

Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available, which is considered a deficiency. These analyses should be obtained in the future.

Other deficiencies visually observed by the inspection team were several rather large rodent holes in the upstream slope, seepage outcropping in both left and right abutment/embankment groins approximately eight feet above principal spillway outlet, and some erosion near the outlet end of the emergency spillway.

Several items of preventive maintenance need to be initiated by the owner. These are described in detail in the body of the report.

Harold P. Hoskins, P.E. Hoskins-Western-Sonderegger, Inc. Lincoln, Nebraska



PHOTOGRAPH NO. 1 OVERVIEW TAKEN FROM LEFT SIDE

PHASE I INSPECTION REPORT NATIONAL DAM SAFETY PROGRAM WELLINGTON-NAPOLEON WATERSHED STRUCTURE C-21 ID NO. MO. 10284

TABLE OF CONTENTS

Paragraph No.	<u>Title</u>	Page No.	
	SECTION 1 - PROJECT INFORMATION		
1.1 1.2 1.3	General Description of Project Pertinent Data	1 1 2	
	SECTION 2 - ENGINEERING DATA	•	
2.1 2.2 2.3 2.4	Design Construction Operation Evaluation	5 5 5 5	
	SECTION 3 - VISUAL INSPECTION		
3.1 3.2	Findings Evaluation	6 7	
	SECTION 4 - OPERATIONAL PROCEDURES		
4.1 4.2 4.3 4.4 4.5	Procedures Maintenance of Dam Maintenance of Operating Facilities Description of Any Warning System in Effect Evaluation	8 8 8 8	
	SECTION 5 - HYDRAULIC/HYDROLOGIC		
5.1	Evaluation of Features	9	
	SECTION 6 - STRUCTURAL STABILITY		
6.1	Evaluation of Structural Stability	11	
	SECTION 7 - ASSESSMENT/REMEDIAL MEASURES		
7.1 7.2	Dam Assessment Remedial Measures	12 12	

APPENDIX A - MAPS

Plate 1 Plate 2 Vicinity Topography Location Map

APPENDIX B - PHOTOGRAPHS

Photographs of Dam and Lake (No. 2 through No. 14)

APPENDIX C - PLANS AND REPORTS

Phase 1	Plan, Section & Profile
Soil Conservation Service	Sheet 2 of 16
Soil Conservation Service	Sheet 3 of 16
Soil Conservation Service	Sheet 4 of 16
Soil Conservation Service	Sheet 14 of 16
Soil Conservation Service	Sheet 15 of 16
Soil Conservation Service	Sheet 16 of 16
Soil Conservation Service	Soils Report
Soil Conservation Service	Geology Report

APPENDIX D - HYDROLOGIC COMPUTATIONS

Sheet 1 of 3
Sheet 2 of 3
Sheet 3 of 3
Inflow Hydrographs
Input Data (PMF, 0.5PMF, 100 YEAR)
Output Data (PMF)
Output Data (0.5 PMF)
Output Data (100 Year)
Principal Spillway Rating
Flow Over Embankment
Total Rating

SECTION 1 - PROJECT INFORMATION

1.1 GENERAL

- a. <u>Authority</u>. The National Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers, to initiate a program of safety inspection of dams throughout the United States. Pursuant to the above, the St. Louis District, Corps of Engineers, District Engineer directed that a safety inspection of <u>Wellington-Napoleon Watershed Structure C-21</u> be made.
- b. <u>Purpose of Inspection</u>. The purpose of the inspection was to make an assessment of the general condition of the dam with respect to safety, based upon available data and visual inspection, in order to determine if the dam poses hazards to human life or property.
- c. Evaluation Criteria. Criteria used to evaluate the dam were furnished by the Department of the Army, Office of the Chief of Engineers, in "Recommended Guidelines for Safety Inspection of Dams." These guidelines were developed with the help of several Federal agencies and many State agencies, professional engineering organizations, and private engineers.

1.2 DESCRIPTION OF PROJECT

- a. Description of Dam and Appurtenances.
 - (1) The Wellington-Napoleon Watershed Structure C-21 is a rolled earth fill approximately 465 feet in length with maximum height of 37 feet. The dam is constructed in the Missouri River loess hills.
 - (2) The principal spillway is uncontrolled and consists of a reinforced concrete (R/C) riser with a 24 inch diameter R/C pipe conduit outlet.
 - (3) The emergency spillway is a vegetated channel cut into loess soils on the left (west) abutment. It has a bottom width of 70 feet and side slopes of 3H on lV.
- b. Location. The dam is located in the northwestern portion of Lafayette County, Missouri, as shown on Plate 2. The dam is shown on Plate 1 in the SE 1/4 of Section 19 and the SW 1/4 of Section 18, T50N, R28W. The lake formed by the dam is shown on Plate 1 in the previously mentioned 1/4 sections as well as the NW 1/4 of Section 29, T50N, R28W.

- c. <u>Size Classification</u>. Criteria for determining the size classification of dams and impoundments are presented in the guidelines referenced in paragraph 1.1c above. Based on these criteria, this dam and impoundment is in the small size category.
- d. Hazard Classification. Guidelines for determining hazard classification are presented in the same guidelines as referenced in paragraph c above. Based on referenced guidelines, this dam is in the High Hazard Classification. The estimated damage zone extends one mile downstream of the dam. Within the first one-half mile downstream of the dam are four to five houses, a Missouri-Pacific railroad crossing and a Highway 24 crossing.
- e. <u>Ownership</u>. The dam is owned by the Wellington-Napoleon Water-shed Subdistrict, 120 West 19th Street, Higginsville, MO 64037. Attention: Chester Temple, Chairman.
- f. Purpose of Dam. The dam was constructed as a grade stabilization, sediment detention and flood water retarding structure.
- g. <u>Design and Construction History</u>. The dam was constructed in 1969. The design and plans for construction were prepared by the Soil Conservation Service (SCS), Columbia, Missouri. Portions of these data are included with this report as Appendix C.
- h. Normal Operating Procedure. There are no operating facilities for this dam. The lake level is controlled by rainfall, runoff, evaporation and the capacity of the spillway.

1.3 PERTINENT DATA

- a. Drainage Area 333 acres (0.52 sq. mi.)
- b. Discharge at Damsite.
 - (1) All discharge at the damsite is through an uncontrolled reinforced concrete box drop inlet and reinforced concrete pipe principal spillway and a grassed earth channel ungated emergency spillway.
 - (2) Estimated maximum flood at damsite unknown.
 - (3) The principal spillway capacity varies from 0 c.f.s. at elevation 758.0 feet to 56 c.f.s. at the crest of the emergency spillway (760.5 feet).

- (4) The principal spillway capacity at maximum pool elevation (763.6 feet) is 60 c.f.s. Maximum pool elevation is that design value for freeboard pool level as furnished on SCS as-built plans.
- (5) The emergency spillway capacity at maximum pool elevation is 1,000 c.f.s.
- (6) The total spillway capacity at maximum pool elevation is 1,060 c.f.s.

c. Elevation (Feet Above M.S.L.).

- (1) Top of dam 765.0 (SCS plans) 764.7 (survey 15 September 1978). The settled top of dam as planned by SCS is 763.6.
- (2) Principal spillway crest 758.0 (SCS plans) 757.8 (survey 15 September 1978).
- (3) Emergency spillway crest 760.5 (SCS plans) 760.5 (survey 15 September 1978).
- (4) Streambed at center line of dam 728±.
- (5) Maximum tailwater unknown.
- d. Reservoir. Length of maximum pool 3800 feet ±.

e. Storage (Acre-feet).

- (1) Top of dam 297^{\pm} .
- (2) Emergency spillway crest 196.
- (3) Principal spillway crest 150.

f. Reservoir Surface (Acres).

- (1) Top of dam 29^{+} .
- (2) Emergency spillway crest 20.2.
- (3) Principal spillway crest 16.5.

g. Dam.

- (1) Type Earth embankment.
- (2) Length 465 feet ±.
- (3) Height 37 feet ±.

- (4) Top width 14 feet.
- (5) Side Slopes.
 - (a) Downstream 2.5H on 1V.
 - (b) Upstream 2.5H on 1V with 20 foot berm at principal spillway elevation.
- (6) Zoning None shown on the plans.
- (7) Impervious Core All embankment material reported to be lean clay (CL) as shown in Appendix C.
- (8) Cutoff Plans show a cutoff varying in depth from 4 to 10 feet with 12 foot bottom width and side slopes of 1H on 1V.
- (9) Grout Curtain None.
- (10) Drains None.
- (11) Wave Protection Vegetated berm.
- h. Diversion and Regulation None.
- i. Spillways.
 - (1) Principal.
 - (a) Type Standard SCS 2' x 6' x 10' R/C drop inlet and a 24-inch R/C pressure pipe.
 - (b) Length of weir 12 feet (2 x 6')
 - (c) Crest elevation 758.0 feet M.S.L.
 - (2) Emergency.
 - (a) Type Standard SCS grassed earth channel.
 - (b) Control section 70 foot bottom width, 3:1 side slopes, 30 feet length.
 - (c) Crest elevation 760.5 feet M.S.L.
 - (d) Upstream channel clear and well grassed (tall).
 - (e) Downstream clear and well grassed (tall).
- j. Regulating Outlets None.

SECTION 2 - ENGINEERING DATA

2.1 DESIGN

Data on the geologic investigation, hydraulic/hydrologic computations, construction plans, and the soil mechanics/soil engineering report were supplied by the Soil Conservation Service, Columbia, Missouri. This information is shown in Appendix C and Appendix D.

2.2 CONSTRUCTION

No construction data were readily available; however, it is reported that the dam was constructed with SCS engineering supervision and standard inspection and quality control procedures.

2.3 OPERATION

No information was available on the maximum loading on the dam.

All spillways are uncontrolled.

2.4 EVALUATION

- a. <u>Availability</u>. The engineering data shown in Appendix C was readily available from the SCS, Columbia, Missouri.
- b. Adequacy. The available data and reported information are considered adequate to assess the design and stability of the structure. Seepage and stability analyses comparable to the requirements of the "Recommended Guidelines for Safety Inspection of Dams" were not available which is considered a deficiency. These seepage and stability analyses should be performed for appropriate loading conditions (including earthquake loads) and made a matter of record.
- c. Validity. The available data and analyses conform with accepted practice. Parameters for embankment strength were based upon conservative values obtained from detailed testing of similar (loess) materials used to construct similar embankments in the same watershed.

SECTION 3 - VISUAL INSPECTION

3.1 FINDINGS

- a. General. A visual inspection of Wellington-Napoleon Watershed Structure C-21 was made on September 15, 1978. Engineers from Hoskins-Western-Sonderegger, Inc., Lincoln, Nebraska making the inspection were: Rey S. Decker, Geology and Soil Mechanics; Garold Ulmer, Civil Engineer; Richard Walker and Gordon Jamison, Hydrology. Results of the inspection are summarized below. Photographs are shown in Appendix B.
- b. <u>Dam.</u> Rough measurements of the profile along the crest of the dam and emergency spillway and cross sections of the embankment and spillway indicate that the structure was constructed according to the plans shown in Appendix C.

The dam is covered with an excellent growth of adapted grasses and legumes.

No cracks, slides or abnormal deformations were noted on the embankment or abutments.

No significant erosion was noted on the upstream face of the dam. However, several rather large rodent holes were observed on the upstream slope.

Surface materials in the dam and abutments consist of lean clays (CL).

A very wet area was noted in the west abutment/embankment groin downstream from about Q station 3+75. Seepage in this area was outcropping at about elevation 750 which is some 8 feet above the elevation of the principal spillway outlet conduit. Seepage was also noted in the right abutment groin at about the same elevation as on the right abutment. Seepage in both abutments seemed to be ponded in the heavy vegetative cover and appeared to be clear.

c. Project Geology. See Appendix C for geology report.

d. Appurtenant Structures.

- (1) Principal Spillway. The concrete in the spillway appears to be in good condition. The lake level was 0.2 foot below the spillway crest elevation at the time of the inspection.
- (2) Emergency Spillway. The emergency spillway is well vegetated with brome grass and vetch. It looked very good with no evidence of erosion in the bottom or side slopes.

Some gully headcutting was noted at the outlet end of the diversion along the west (left) side of the spillway.

- d. <u>Reservoir Area</u>. No wave wash, excessive erosion or slides were observed along the shoreline of the reservoir.
- e. <u>Downstream Channel</u>. The channel downstream from the emergency spillway is overgrown with trees and brush. However, spillway discharges from this dam are collected in the reservoir just downstream from this structure.

3.2 EVALUATION

None of the conditions observed indicate a need for immediate remedial action. Additional studies would be required to evaluate the affects of seepage on the stability of the structure. Erosion at the outlet of the west spillway diversion could encroach on the emergency spillway if left uncontrolled. Trees in the channel downstream from the emergency spillway should not affect the operation of the spillway. The discharges from this dam are impounded by a downstream reservoir in which high water levels will almost impinge upon the downstream toe of this structure.

SECTION 4 - OPERATIONAL PROCEDURES

4.1 PROCEDURES

The pool level is controlled by rainfall, runoff, evaporation and capacity of the uncontrolled spillways.

4.2 MAINTENANCE OF DAM

The dam is reasonably well maintained. Action should be taken to correct the minor deficiencies noted in Sections 3 and 7.2.

4.3 MAINTENANCE OF OPERATING FACILITIES

There are no operating facilities at this dam.

4.4 DESCRIPTION OF WARNING SYSTEM IN EFFECT

The inspection team is not aware of any existing warning system for this dam.

4.5 EVALUATION

The dam and appurtenances appear to be well maintained with the exception of some laxity in controlling erosion near the outlet of the emergency spillway.

SECTION 5 - HYDRAULIC/HYDROLOGIC

5.1 EVALUATION OF FEATURES

- a. Design Data. Detailed plans for the structure were furnished by the SCS. Pertinent hydraulic and hydrologic data which were taken from as-built plans furnished by the SCS are tabulated in Sections 1, 1.3 and in Appendix D as hydrologic computations. The supporting computations are attached.
- b. Experience Data. The drainage area, reservoir water surface areas, and elevation-storage data were taken from the SCS asbuilt plans. The hydraulic computations for the spillway discharge ratings were based on data taken from the as-built plans. The hydraulic computations for the dam overtopping rating were based on data collected during the field inspection in order to reflect settled conditions.

c. Visual Observations.

- (1) Principal and emergency spillways are in good condition.
- (2) The emergency spillway does not appear to have ever been used.
- (3) The emergency spillway and exit channel are in the left hillside at the end of the dam. Spillway use should not endanger the integrity of the dam.
- d. Overtopping Potential. The spillways are too small to pass 50% of the probable maximum flood without overtopping. The spillways will pass 40% of the PMF without overtopping. The 100-year (1 percent) peak outflow discharge is approximately 37% of spillway capacity. The results of the routing through the reservoir are tabulated in regards to the following conditions.

Frequency	Peak Inflow Discharge 	Peak Outflow Discharge c.f.s.	Maximum Pool Elevation	Freeboard Top of Dam Min. Elev. 763.4	Time Dam Overtopping Hrs.
100-Year	690	360	762.0	+1.4	~
1/2 PMF	1630	1290	764.0	-0.6	1.0
PMF	3310	3200	765.3	-1.9	3.8
0.40 PMF	1290	970	763.4	0	_

According to the recommended guidelines from the Department of the Army, Office of the Chief of Engineers, this dam is classified as having a high hazard rating and a small size. Therefore, the PMF is the test for the adequacy of the dam and its spillways.

The St. Louis District, Corps of Engineers, in a letter dated 11 August, 1978 has estimated the damage zone as extending one mile downstream from the dam. Within the damage zone are four to five houses, one railroad crossing and one State Highway crossing.

SECTION 6 - STRUCTURAL STABILITY

6.1 EVALUATION OF STRUCTURAL STABILITY

a. Visual Observations. Minor maintenance features that could affect the long time safety of the dam are discussed in Section 3.2. Additional studies are required to evaluate the affects of seepage in the downstream abutment groins upon structural stability of the dam.

Hydraulic/Hydrologic analyses presented in Section 5 indicate that the dam will be overtopped by the probable maximum flood. Under those conditions, water would flow over the top of the dam to a depth of 1.9 feet \pm for about 3.8 hours.

b. <u>Design and Construction Data</u>. The engineering data, analyses, and plans supplied by the SCS conform with accepted practice and are considered adequate to assess the structural stability of the dam.

There is no reason to question the adequacy of construction supervision and quality control.

- c. Operating Records. There are no appurtenant structures that require operational functions.
- d. <u>Post Construction Changes</u>. The inspection party is not aware of any post construction changes.
- e. <u>Seismic Stability</u>. This dam is located in the Zone l seismic probability classification area. An earthquake of this magnitude is not expected to cause structural failure of this dam.

SECTION 7 - ASSESSMENT/REMEDIAL MEASURES

7.1 DAM ASSESSMENT

- a. Safety. The probable maximum flood (PMF) will overtop the dam, however, the spillways are adequate to pass the flood resulting from 40% of the PMF without overtopping. Seepage observed at the downstream toe could affect the long-time stability of the structure. Rodent holes on the upstream slope could lead to potential of failure if left uncontrolled.
- b. Adequacy of Information. The information presented in this report is considered adequate to assess the safety of the structure. Seepage analysis were not found, which is a deficiency that should be corrected in the future.
- c. <u>Urgency</u>. There does not appear to be an immediate urgency to accomplish the remedial measures discussed in Paragraph 7.2.
- d. <u>Necessity for Phase II</u>. Phase II investigations are not considered necessary for this dam.
- e. <u>Seismic Stability</u>. An earthquake of the magnitude to be expected in this area should not be hazardous to this structure.

7.2 REMEDIAL MEASURES


a. Alternatives.


- (1) The size of the present emergency spillway should be enlarged or a supplemental spillway constructed on the right abutment to pass the probable maximum flood without overtopping the dam.
- (2) Additional analyses should be made to assess the affects of seepage on the stability of the structure.
- (3) The owner should engage the services of an engineer experienced in the design of dams to design an adequate spillway system and to evaluate the affects of seepage on the structural stability of the dam.

b. 0 & M Maintenance and Procedures.

(1) A program of regular inspection and maintenance should be initiated. The program should include measures to repair and control rodent holes and to control future tree growth (none observed at this time) on the embankment and to evaluate the progress and possible future affects of gully erosion near the outlet of the present emergency spillway. The grass on the embankment should be routinely mowed to enable early detection of rodent holes.

APPENDIX A MAPS





APPENDIX B PHOTOGRAPHS



PHOTO NO. 2 LOCKING DOWNSTREAM IN EMERGENCY SPILLWAY



PHOTO NO. 3 LOOKING UPSTREAM IN EMERGENCY SPILLWAY



PHOTO NO. 4 DAM AND LAKE TAKEN FROM LEFT SIDE




PHOTO NO. 5

STA GULLY EROSION

IN LEFT SIDE

EMERGENCY SPILLWAY



PHOTO NO. 5 UPSTREAM SLOPE FROM APPROXIMATE CENTER LINE



PHOTO NO. 7 DOWNSTREAM SLOPE FROM APPROXIMATE CENTER LINE



PHOTO NO. 8 CREST OF DAM TAKEN FROM RIGHT ABUTMENT



PHOTO NO. 9
RODENT HOLE
IN UPSTREAM SLOPE.
APPROX. STATION 3+00




PHOTO NO. 10 PRINCIPAL SPILLWAY RISER




PHOTO NO. 11 LOOKING UPSTREAM FROM CREST



PHOTO NO. 12 LOOKING DOWNSTREAM FROM CREST




PHOTO NO. 13
OUTLET END OF
PRINCIPAL SPILLWAY




PHOTO NO. 14 UPPER END OF SEEPAGE SPOT AT STATION 0+50±

APPENDIX C PLANS AND REPORTS Note: Reproductions of plans and reports included in Appendix C are the best possible from copy furnished by Soil Conservation Service. Unreadable portions on the reproduced sheets are also unreadable on sheets from which the copies were made.

CHILL LY LY SOM - His viets Lane CLIFCAL & INCHASE WARRICK In 4. 3 . 9 . Deriver engry desport air MINN BYNINY " 'n . 6 PIC Pas, EAN 766 7 WILL BY PICKOWN

Quantille


WALLET LINE IN THE BEST OF THE


Morrison of the state of the term of the state of the sta


LAIMFILE COULT INSCHA


U. S. DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

\$6.25.00










Entransion to Control
The state of the s
The state of the s
The state of the s



Memorandum

TO : James M. Dale, State Conservation Engineer, DATE: October 28, 1966

SCS, Columbia, Missouri 65201

: Roland B. Phillips, Acting Head, Soil Mechanics Laboratory,

SCS, Lincoln, Nebraska 68508

SUBJECT: ENG 22-5, Missouri WP-08, Wellington-Napoleon, Site No. C-21 (Lafayette Co.)

ATTACHMENTS

1. Form SCS-354, Soil Mechanics Laboratory Data, 4 sheets.

2. Form SCS-127, Soil Permeability, 2 sheet. Form SCS-128, Consolidation Test, 5 sheets. Form SCS-128A, Log Time Consolidation, 3 sheets.

3. Form SCS-355A, Triaxial Shear Test, 1 sheet.

4. Form SCS-352, Compaction and Penetration Resistance, 4 sheets.

5. Form SCS-357, Summary - Slope Stability Analysis, 2 sheets.

6. Investigational Plans and Profiles.

REVIEW AND INTERPRETATION OF DATA

FOUNDATION MATERIALS

A. Classification: The site consists of Loess in the abutments that classes as CL and alluvium in the valley bottom that classes as CL and ML with some deep sands. There is a CH at about a 30 ft depth.

An area of organic silt as thick as 20 ft is noted from the channel toward the left abutment.

B. Dry Unit Weight (Blow Count): Four undisturbed core samples were submitted. Three were from the surface ML and CL alluvium and ranged in dry unit weight from 1.37 g/cc to 1.56 g/cc with blow count from 2 to 5 blows per foot. One was from the deeper organic silts and ranged from 1.07 g/cc to 1.08 g/cc but at 14 blows per foot.

All the blow counts ranged from 2 to 11 blows per foot in the alluvium. from 9 to 20 blows per foot in the organic silt and from 18 to 20 blows below those silts.

C. Consolidation: Consolidation tests were made on the CL sample 67W326 from a 10 ft to 11 ft depth and on the ML (organic silt) sample 67W328 from a 22 ft to 23 ft depth.

The CL was at an initial density of 1.47 g/cc and a consolidation potential of abou .025 ft/ft is indicated under the fill at floodplain level.

2 -- James M. Dale -- 10/28/66

Roland B. Phillips

Subj: ENG 22-5, Missouri WP-09, Wellington-Napoleon, Site No. C-21

The ML was at a density of 1.18 g/cc and a consolidation potential of about .020 ft/ft is indicated. The potential would be very high under a high fill. The sample may have been slightly disturbed in sampling so its potential is actually assumed as .015 ft/ft. This indicates a total foundation consolidation of 0.65 ft at ξ Station 4+50. A maximum horizontal strain of .007 ft/ft is computed with b = 200 ft, h = 36 ft, and d = 32 ft for the 2 1/2:1 slopes and 10 ft berm as proposed.

D. Permeability: Rates were determined for the CL and the organic ML during consolidation. They are K = .024 ft/day for CL and K = .0035 ft/day for the ML. These rates were obtained by extrapolating values found after consolidation to the in-place density of the sampled materials.

Rates for the sands will be higher. The SP may correlate to the SP-SM from sites No. B-21 and C-22 for which rates of $K=10.0\ \text{ft/day}$ were estimated.

E. Shear Strength: A consolidated, undrained triaxial shear test on the $\overline{\text{CL}}$ sample, 67W326 (301-9), yielded shear parameters of $\emptyset = 18^{\circ}$, c = 750 psf at a test density of 1.49 g/cc. This is considered to be a limiting foundation strength.

EMBANKMENT MATERIALS

- A. Classification: Borrow samples submitted all class as CL though surface materials are more silty.
- B. Compacted Dry Densities: Standard Proctor compaction tests, (ASTM D-698-A) yielded maximum dry densities from 103.0 pcf to 105.0 pcf.
- C. <u>Permeability</u>: No tests were made. Based on classification, compacted materials will have low permeability rates.
- D. Shear Strength: Shear strength for the embankment CL materials is correlated to like materials from sites B-21 and C-23 with $\emptyset = 10^{\circ}$, c = 1150 psf for the most plastic and $\emptyset = 17^{\circ}$, c = 925 psf for the less plastic material.
- E. Consolidation: No tests were made. Based on the classification of materials residual settlement within the fill should not exceed 2 1/2% of the fill height.

3 -- James M. Dale -- 10/28/66
Roland B. Phillips
Subj: ENG 22-5, Missouri WP-08, Wellington-Napoleon, Site No. C-21

SLOPE STABILITY ANALYSIS

Slopes stability was checked by a circular failure method both for a 35.3 ft embankment only and for 23 ft of foundation. The most critical case was found for failure through the foundation but a minimum upstream safety factor of 1.67 was computed for the 2 1/2:1 slope under full drawdown effects. This is a very rigorous analysis and the results indicate the 2 1/2:1 slopes are satisfactory.

SETTLEMENT STRAINS

Settlement strains should not cause high differentials if steep banks are sloped to 3:1 or flatter and no soft material is left under the fill.

CONCLUSIONS AND RECOMMENDATIONS

A. <u>Cutoff</u>: A shallow cutoff trench (3 ft - 6 ft) is recommended to intercept the surface ML and any surface disturbances such as root holes and animal burrows.

Backfill with CL placed at 95% of standard.

B. Principal Spillway: The pipe cradle can be set on relatively firm silty CL without over excavation. The trench should have a wide bottom and 3:1 side slopes or flatter.

Backfill at high density near the pipe but feather out away from it to fit the 95% of standard used in the fill.

Base pipe joints on a maximum horizontal strain of .007 ft/ft.

Use $\emptyset = 25^{\circ}$ for conduit loading computations.

- C. <u>Drainage</u>: Drainage is not needed for slope stability. It is not recommended.
- D. Embankment Design: Provide a homogeneous fill of the available CL borrow placed at 95% of standard density. Control moisture at two percentage points below optimum to three above.

Use 2 1/2:1 slopes with the proposed 10 ft upstream berm at about elevation 75%.

Provide overfill of 1.4 ft from & Station 4+00 to 5+50 to compensate for residual settlement of 0.65 ft in the foundation and 0.75 ft within the fill.

cc:
James M. Dale (2) E. S. Alling
Gerald McElhiney D. S. McVicker

7 • ٠; 146/219 2.00 121 121 139 23.2 110 12 Sec. 0.36 medium diaser Printabales Composition of the comp 5/2 Circ į 6 41 43 015 VEBS108 A STATE OF 20 7 20) ز 5 4 MC UB19160 CL#55 (FICE FIGE ٤ ۲ SM 3 7 ... 5 11 Ξ 3 8 = . į 5 Q ! <u>=</u> - 4 Ì ÷ ;; GRAM SIZE DISTRIBUTION EXPRESSED AS PERCENT FINER BY DRY METENT i í .27: ×3 í 1455 "BS DEPARTMENT OF THE MOND SOLL CONSERVATION SERVICE FUR. . . श्च 3 66, 90/ 3 5 % 19/00 2: 2: 33 76 98.0 300 77 976 : 3 23 21 7 15 90 37 3062 . 37 2 21 47 92 1115 29.0 63 14 43 7 3 9 11. 5003 13 6 35. 7 ·a 71 2.1 Č٨. FIELD CCASS 70 7 ďΚ 21 ঘ Z 30-31 25-261 35.51 35.5 5.5 10.5 96 F F K Core j 18 į Jan 1 Site No. 11.5 1.2.17 140 نَ 0111 01+1 9 04+4 Wellington-Napoleon £ 1111 35. ۲. در MISSOURI £ F111 £ F111 £ PILL 7.3 4 5111 301-3 301-5 301-6 301-4 301-7 301-8 Fritt B 1-18-55-358 7-19-66 Same (**674** N a N 8 ഒ Ž,

								67:														į	: 	i
ĺ		J	184		141,			255									٠.					1		! !
	UNEISTURBED SAMPLE DATA		, ii.	20.5			100	5.8			32.2			177342		-	40,			100				
	21382		Ser our	1.37				1.05			(3.2)			0.0			٦٥.			13.				
ſ	P Serv	9	Densite mich	." //				2."									7	-				1	<u> </u>	1
	MGISTONE DEBSTTY MELAPIGNSMIPS (7) STANDAND	Car Contract	15.67	,×				$\neg \neg$					\top						1			1		
- {			3 3 8 8	2%				Z W.Z	_															1
				80			1	45		Ì											1	-	!	!
		SAUDIE	N. C.	2				14			9			0			0			હ	į			1
		CLASS -		MC				Ĭ			ž			7			7			Σ				1
	ATTERBERG LIBITS		ī	9				80			7			7/						1]
	<u> </u>	\perp	=	35			_	47			13		_	36					1	15	_			
			, 1/2. 5°					-			 			+		\vdash			-		\dashv	-	_ <u>i</u>	1
		ಪ	13.6					\dashv	+			_	 -						+		\dashv		+-	1
	#E 15#	CRAYEL	3/4.																					1
	100		.27.										_	+						\sqcup	\dashv	 -	-	1
	3111		3/0					-	\dashv	+-				++			_	-	+	-	+			1
314 Constant to the constant	PERCENT		¥ 8	Cal				3			18	-	\dagger	00/	1	1	-8		+	19		1	+	1
.	SSED AS	SANDS	8.5					A					\perp	\prod			A		I					
	MECHA Da Expre	3	50 042	1				\mathcal{H}			/	 -	+-	+/+			4		-	/	\dashv			-
5	STRABUL		6:05 0250	/-		-	-	/-	_		/-		+	$\forall +$			/-	+	_	/		+	+	1
	MECHANICAL ANALTSIS CDAIN SIZE DISTRIBUTION EXPERSED AS PERCENT FINER BY ORY	_	# 200 0 014	16				89			32			16			93			23	\dashv			
1	85	<u>.</u>	ç 68 200	28 63				13.02		4-	37.36	-	-	19 04			18 86		-	48.62	+	-		-
!		Same	6000	2/2				200	-	+-	223	-	+	£23			19	-	-	25.4	\dashv	+	+-	1
ı			966					6,			e,			77										1
		CLASS CLASS		75				71			711/			W			ML			7.				
	_	MI 430	-	15 - 16.51	-			23.5.			20-21,	-	+	10-11,			20-21		+	15-16'				
	_				_			ଥ ଯ			8	+	+	1 2	+-	H	2			=	-+			1
			Site No. C-21	Sore				Core			Jar			Jar			Jar	1::		Jar				
			Site							}								1/225						
		**						9+40			}							2						1
		LOCATION AND DESCRIPTION	9	9				04+4	,		2+40			1465			1+65	on Cross		2+50	}			1
		5-	poleo						3,006,00									ايا						
			on-Na						6,0	İ	Sprox.			Spry.	.		Spvy	Organic			ì	į	:	:
		MISSOURI	Wellington-Napoleon	# F111				€ F111			f Prin. Spwy.			f Prin. Spuy.			Prin. Spuy.	0		F111			<u> </u>	
								Ī			1-1	_	-	- a-				-		-	-			-
9		e i E t B		01-10				301-11			305-3			304-1			304-2			4.2		į		_
7,19,66		1488441387 Sample		12				328			329			Q.F			131			33				
	ــــــــــــــــــــــــــــــــــــــ	<u> </u>		<u> </u>		1	<u>.</u> 1				لــــــــــــــــــــــــــــــــــــ			4-4		لــا				 l				-
•								-	-					 چرک پوؤم	See See See		-		in the same		- 1	***	والمراجعة المراجعة	نظ

U S DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

2.63 3 H. J.S. of Description of Descriptio बट्टिट्रन्ग<u>)</u> (55) 263 57. 35.1 168 147 18.0 103 5 UNITED SAUME PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS PRICES
ACTION SAUS 3 2 3.5 ĭ 5 기 ATTERERG 4 9 = 77 2 3 E **E** 1 28 ¥ % € MECHANICAL MARYSTAN ENPERSED AS PERCINE FINER BY GRY WEIGHT -2/1 -5/5 346 650 670 646 8 3 Ś \mathcal{R} 9 0520 50:5 5.60 500 200 09:0 09:0 022:0 26 45 33 39 15 18 36 69 74 22 42 82 91 13 18 37 03 92 27 % 3005 91 9 22 71 20 FELO CLASS SPEATION 70 W 77 20-21 25-26 30-31 35-36' 15 Site No. C-21 L. Bak 7 78 Ş in an ala place A+50 4+50 \$1 5.5 2,50 5+30 Wellington-Napoleon MISSOURI THIT ¥ € P111 £ P111 £ F111 Borrow **6**-3 7 2.5 9-4 101-1 Jone X1- 114 1-16 7-13-66 Transland Transland Weekle Ħ 333 674 336 4 335

U S DEPAKTMENT OF ACMICULTURE SOIL CONSERVATION SERVICE

2.63 MEISEGNE DEMBITY MEI AT LASHIPS MED DIANDAR CT MADIFIED 18.5 5 91 2 105.0 1000 130 (%) **©** 2015 8015 8015 Struct CLASS. 77 7 3 3 100 7 ATTERNIBE CONTS 2 = 36 4 -2 × . GRAIN SIZE DISTRIBUTION ERPRESSED AS PERCENT FIRER BY DRY MEIGHT Ì \$5 *3 ; ; 8.5 3 001 8 82 040 820 000 SAMDS 35.2 8 8 0.520 51 87 95 47.86 91 51.38 603 20 € 5381 6000 22.28 22 28 20 22 CLASS SCATGE 75 77. 70 1-1, 0-4-4-9' " Set set 2 Kit L. Beg 10.50 m. 1.40 is is a yello compacted C+00 0+12 LOCATION AND DESCRIPTION 6+75 1350 24 4ta Wellington-Nepoleon 0 1 2 MISSOURI Borrow Borrow Borrow 103-1 103-2 102-1 1 7-19-66 1.50 E3- 330 38 3 2 R


30/-9	EPTH, GEOLOGI 10-11.5 ESTED AT	C ORIGIN 4 F	DATE
	11NCO/N 37 PI /3 1.47	TEST SPECIFICATIONS	
COMPRESSION INDEX. C.			
0.1	1.0	, po	100
0.25	¥9•		
0.70			Δ-
0.70			,
0.60			<u> </u>
			2
59			
CONSOLIDATION (CV)			
0.1 02 03	0.4 0.5 1.0 2	20 30 40 50 10 SOLIDATING PRESSURE & S.F.	20 30 40 50 100

TE		U. S. DEPARTMENT of ACSOIL CONSERVATION		LOG TIN	ME ATION
,	UECT and STATE		. ~ .	SAMPLE LOCATION	
	D SAMPLE NO.	QEPTH GEOLOGIC			
•	E OF SAMPLE	TESTED AT	APPROVED BY		DATE
7					
		203 tut (200		000008	
ر اخ		7		ocota ocoea	
30.400		7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7			
DIAL READING 2, 1000		× (t;		000	
INITIAL DI	252	J			
=	3000			TIME (sec.)	•
Ē				000	
d				~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~ ~	
				05	
SPECIME		25			
OF TEST				111776	
INITIAL THICKNESS OF TEST SPECIMEN	03500		033300 03250	0.3326:0	
INITIA		AL READING (in)	ia		REMARKS

TE	MATERIALS U. S. DEPARTMENT of AGRICULTURE CONSOLIDAT											
1	D SAMPLE NO. DEPTH GEOLOGIC ORIGIN											
FIEL	D SAMPLE NO.											
TYP	e of sample											
14	<u> </u>	1////30/-9	1									
		∞ y99										
Ë		oocs oocs										
220			1 2 4 5 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1									
READING 0. 4000												
DIAL READ		6 0000 0000										
INITIAL DI	7.25Z.E		1 									
2	2027	096 300 W	4 4 4 4									
. E.	504											
d/: N												
SPECIME		02										
OF TEST :	(45)											
INITIAL, THICKNESS OF TEST SPECIMEN	0.325.0	03120 03100 032250 0.2250 0.2250										
N T		DIAL READING (in)	EMARKS									

	HATERI TING R				MENT of SERVATI			SOIL PER	RMEAB	ILITY
1	CT and STATE		10.20	1/501/	- C-2/ /	Miccon	21	SAMPLE LOCATION		
FIELD	301-9			0 - 11.5'		OGIC ORIGIN		10777	1179	
1	OF SAMPLE	3.5.D	TESTE	INCOLI	N	APPRO	YE GAY		DATE	
	SSIFICATION					LL <u>3</u>	7PI <u>/3</u>	SPEC	IFIC GRAVIT	Y
	TEST	NQ.		ووليع	1,2,	3-0	4	G _s (-)#4	2	.65
INIT	IAL MOIS	TURE	%			1		G _s (+) #4		
DRY DENSITY 3 9/ce 1.49 1.51 1.56 Gm(Bulk)(+) #4										
VOI	D RATIO			0.7801	0.7525	0.7525		TEST SPECIFICAT	TICNS	st on The
PER	RMEABILIT	Y COEF	200	0.024	0.0042	0.0013		Test specifical Fielding Head Consolidatio	م دروع با	ا عد
	COLATIO									
7/	DURING	TEST			<u> </u>					
VOID RATIO (e)	0.50				8		00	90	Q	889
REM	MARKS									
					•					

MATERIAL TESTING REP	S U. S. DEPARTMEN ORT SOIL CONSERV	T of AGRICULTURE VATION SERVICE	CONSOLI	DATION TEST
PROJECT and STATE	- 100 1 and 10-21	14155001	SAMPLE LOCATIO	on 3ta 4440
FIELD SAMPLE NO.	- 4351604 C-21	GEOLOGIC ORIGIN	<u> </u>	
TYPE OF SAMPLE	22.0 -23.5 TESTED AT	APPROVED BY		DATE
CLASSIFICATION	ro SMI - LIM	TEST	SPECIFICATIONS:	
	LLPI_		or gon roansons	
	r _d 1.13			
	ATIO, e. 1./6/2	-		
COMPRESSION IN	DEX, Cc			
0.1	a.ı	,	ю	ю
1.15				/2
		7		
1.10			V: III Z	70
3/:05				2 Arman
9 1.05			12/	NSON
L				8
g /. 00				PERCENT CONSOLIDATION
0.95				4 ~
0.90				ک
.3				
COEFFICIENT OF				
FICIE				
S S S S S S S S S S S S S S S S S S S				
l °				
0.1 0	z 03 04 05 i.0	20 30 40 50 CONSOLIDATING PRESS		30 40 50 100
REMARKS	i	,		
			•	
			•	
1				



TE	M. ST	ATE ING	RIAL REP		U.S												CC	NC	OC SC	G (ΓΙΝ DA	IE TION
PRO	ECT	and S	TATE JNG	T0:	J - /	VA :	201	60	~		- :	2 /	M	 ، دد،	ગ્ <i>તા</i>	 ri	SAM	PLE LO	CATIC	N		
FIEL	D S	MPLE	NO.		I DEST	0'-			1.6	EOLOG	ic 0	RIGIN			-							
		SAMPL	rbe		TEST	ML.				10		APP	ROVE	BY							OA	TE
	10	12.14	7 0 0	<u>. </u>						<i>///</i>		<u></u>		_								1
									•											00005	•	
.s.	-												1 1 1 1							0000		
0.400															1					000>		•
1 1														/						2000		
DIAL READING									psf	-		~								000		
INITIAL DI			1 1						0009/	-1-	1	7	1						1.11.1	096	(sec.)	· ·
2						11			7	7		11	:	1			<u>: </u>		i	00Z	TIME (sec.	· · · · · · · · · · · · · · · · · · ·
.달.																			·	, 001 08		
0																	1			o ,		
Z						1														oz		
SPECIMEN																				oı		•
OF TEST			2																	¢		
INITIAL THICKNESS (0.3350	, ,	03300	03250		0.3200		0.3150		0.3100		0.3050		-0.3050		0.295.0		-	2		
INIT.		<u>—</u>					(D)) PN	IIQA	38 -	JAIC	}										REMARKS

MATERIALS UTESTING REPORTS	. s. depart OIL CONS				SOIL PERM	EABILITY
PROJECT and STATE	• / • •	_	~ ~ /	11	SAMPLE LOCATION	
WELLINGTON FIELD SAMPLE NO DI	- <u>NA POL</u>	-EON	C-2/-	111550	<u>ori (</u>	
1020 324722 110	<u> 22.0- 23.</u>	.51				
TYPE OF SAMPLE UNDISTURSED				VED BY		DATE
CLASSIFICATION	3/110- 2	INCOL.	<i>N</i> :		1	
CLASSIFICATION			LL	PI	SPECIFIC	GRAVITY
TEST NO.	ı	2	3	4	G _s (-) #4	
INITIAL MOISTURE	%				G _s (+) [#] 4	
DRY DENSITY 0 g/cc					Gm(Bulk)(+) #4	
VOID RATIO	1.1420	1.1/17	1.0441		TEST SPECIFICATIONS	}
PERMEABILITY COEF		.0027	0020			
PERCOLATION COEF	1				{	
H/L DURING TEST						
(e) 1.15 (A) 1.00 (A) 1.05 (A)	K = 003	\$	ay	a COEF (k		009

				PARTMEN ONSERV				TRIAX	IAL S	HEAR	TEST		
PROJECT and		, A 1 = . 1 2	6.200	او روس ای	15. 19- 21	I MAICE		T T	E LOCATION مرکز ک	-11º			
FIELD SAMPLE	NO.		DEPTH ,		GEOLOGIC								
TYPE OF SAI	MPLE		TESTED AT		, ,	DATE CEVORAGE							
04,5,5-			TEST DA		· / //			SPECIMEN	DATA		TYPE OF		
				<u>"フ</u> ; PI		HEIGHT	TEST						
% FINER	(mm)			.; C.OO5 _	<u>23</u> :	ł			SSED <u></u> TION <u></u>		υυ <u> </u>		
G _s (-*4)	ے.		(* 200) : Ge (+		1	ME INO							
				pcf; wo_	%	MOLDIN		co 🗔					
MODIFIED: Yd MAX. pcf; Wo % MOLDED AT % OF Yd MAXIMUM													
DRY D					JRE CO!			TIME OF	-	DEVIATOR	1		
INITIAL pcf	DA	SOLI-		START	DEG. OF S	i		CONSOLI- DATION	PRINCIPAL STRESS		STRAIN AT		
g/cc 🗔	g/c			TEST	OF TES	ST TE	ST	(hrs.)	σ ₃ (ρsi)	(psi)	ε (%)		
1.20	1.3	-7		7.1.4	1 -2-1			101.50	1 3	1/5.5			
1.50	1.	()		1 75.7	1 /2 32			19.60	ت ً.	[;;-,-,-	<i>3</i> 7		
1,200	1 :1	55		28.0	- 25g .		/	29.59	J & C	1 <u>2007</u> 1	20		
		<u>-</u>			DEVIAT	OR STR	ESS	$(\sigma_1 - \sigma_3)$,	psi	<u> </u>			
	0) 		20	<u> </u>	20		50	<u> </u>	73	Po !		
%			7							-			
(3)		1005				7-7							
A!N	10					=\=	\						
STRAIN			1019					2	7				
	20		-7073										
					0451/1	<u>/</u>							
		SHE	EAR PARA	METERS									
		0	_/5	——— "c.a. C							,		
•		ion c	0 <u>25</u>										
psi	_												
(2)	رت		₹ <u>-</u> : <95	225									
) 53													
IRES	10												
8				== /==									
SHEAR STRESS (C), psi		/==											
Ω	٥,)	10	20'	≥0	ن		<u> </u>	60	ر د د	ر د د		
051110			·	·			TRESS	5 (a), psi		3 1511			
REMARKS	7.	STE	73 ^{17, بي} ن 9	real w	1000	•				•			

** *** **** **** ****

U.S. DEPARTMENT of AGRICULTURE MATERIALS TESTING REPORT SOIL CONSERVATION SERVICE PENETRATION RESISTANCE Missouri FIELD SAMPLE NO 0.0 -5.0 A+50 ; 4+50 APPROVED BY DATE GEOLOGIC ORIGIN SML-LINCULA CLASSIFICATION PI 10 CURVE NO. < 7 MAX. PARTICLE SIZE INCLUDED IN TEST STD. (ASTM D-698) 定: METHOD _ 2.63 (MINUS NO. 4 MOD.(ASTM D-1557) [METHOD] SPECIFIC GRAVITY (Gs) PLUS NO. 4 OTHER TEST [(SEE REMARKS) 2500 RESISTAIICE, 1000 PENETRATION 500 133 193,570: MAX. Te 13,0 CPT. MOIST. 123 SOIL, 120 COMPACTED 1/5 1/3 105 DRY DENSITY DENSITY 105 40% REMARKS

MANGE 0185 1911

COMPACTION U. S. DEPARTMENT of AGRICULTURE MATERIALS TESTING REPORT SOIL CONSERVATION SERVICE PENETRATION RESISTANCE M135 0211 FIELD SAMPLE NO. 6+75 Borron C+00 0.0 -9.5 103.1 TESTED AT GEOLOGIC ORIGIN APPROVED BY SML- LINCUL CLASSIFICATION CURVE NO. MAX. PARTICLE SIZE INCLUDED IN TEST STD. (ASTM D-698) X: METHOD MINUS NO. 4 MOD.(ASTM D-1557)□; METHOD SPECIFIC GRAVITY (G.) PLUS NO. 4 OTHER TEST [(SEE REMARKS) psi 2500 RESISTANCE, 2000 1500 1000 PENETRATION 500 123 104.5 - :: MAXI 73 10.5 OFT. MOIST. 123 MATURAL COMPACTED SOIL, pef //5 110 105 ببرر DENSITY 15 45% 23 acabeur. REMARKS

MATERIALS TESTING REPORT	U. S. DEPARTMENT SOIL CONSERV			N AND RECISTANCE
PROJECT and STATE Wellington	LOCATION	# C. 2!	Missouri	į
FIELD SAMPLE NO. 103. Z	BONOW	C+00;	6+75	JEPTH - 9 0
GEOLOGIC ORIGIN	_	TESTED AT SML-LINGULY	APPROVED BY	DATE
CLASSIFICATION	<u> </u>	40 PI 17	CURVE NO. 4	OF <u>4</u>
MAX. PARTICLE SIZE			STD.(ASTM D-698) ②; M	
SPECIFIC GRAVITY ((a) { MINUS NO. 4 _ PLUS NO. 4 _		MOD.(ASTM D-1557)□; M OTHER TEST □ (SEE RE	-
2500				
A 2000				
RESISTANCE 12000				
RE ST				
Z 1000				
PENETRATION 500				
DE NOTICE DE LA CONTROL DE LA				
125			MAX. Ya	103.0 3.1
120			+ CPT. 110.57	
0 0	Lids Bills		NATURAL 1	:07 %
	right.	4		
soil.				
0 1/0				Co.
S 105				COMPLETE SATURATION OR
	+ DRY CENSITY	0		AIR VOICE CUR OR -
ö 100		0		1/2 CURIE OR
Z Z Z				
	0			45%
90				
85				
8	10 /2 /4	- 14 18	20 22 27 27	26 30
REMARKS	TO STUNE	upingni, Pikol Paulini	.N. OF 177 (177) - Holo Della Carlos	e james (f. 1919). Standard (f. 1919).

Γ	MA	ATERIALS	U. S. DEP	ART	MENT	of A	GRICU	LTU	RE		UN								
		NG REPORT		-							'AE		TI.	Y					
	69/	end state <u>C.'.M.STOW-</u> Of analysis	NA.20.	<u>ع ۽</u>	ファノ :	5/7.	MALYZEO	21, AT			つくべ		APPR	OVED		9	2:ق-	<u>フー:</u>	55
	52	UEDISH C	CIRCL	€.			S.M.	<u> </u>	1-11		ひんと	 - إ						1 1	 -
	Ĺ			u.		3.0		177		1.67	1,0,1		24						-
REMARKS	Sat. Sher		·		Sinh		forn			+->	STOWNSHIT	thru							
	(psd)	027/		į	11-14		17.77				ado 1	Ichor							
	ton	2355 2475 0.335			1.485		should v			2).	11:20 (50)	hou				-			
N DATA	• (Bob.)	120			Station 4.4		white		. 7.7	6/25	77:		1/30						
DESIGN	7sub (pcf)	56.5 53.0 60.5			3/0				,	097	-112 C	Š	3.06-						
ADOPTED	Yeat (pcf)	1190		CONDITIONS	S (6) C10		fion		17 - 6	172211	0.000	Fren	nd_M						
	Ym (pct)			COND	Section (0)	•	. 1		01000		77.0	2017	-001110		-				
	()od)				7		Alic			£230	000	1/12	,0,						
CL ASSI-	FICA-	70,000			Heximum 11 Arc	77	2002 2007	5777		3)6	3/32/2	11/2							
	AND USE OF MATERIALS	Eczined (has 546"0-23) Emb (has 546"6-21)			Metallorical and the Merin	(10°-1150)011/11	No dinin - Not		d'Ol mondenning	thru Emb (170°- 52	Fulldistriction=10.	No chrim-No de	Frub (17.0°-925)						
	SOURCE	9		SLOPE	1:32	1/2			1.76			7			;	!	 		[: :
		0000	<u> </u>	TRIAL NO.	190		기 기 기	-	2 7/), I.	27	S. N.	;			-			<u> </u>

Convincion of Succession of Call Welling our Harason of Call Miscount Mark Section of Succession 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2		
Mail Section © 5.7. 4-35		Constitution of South 1 of E Section
Mail Section © 5.7. 4-35	and the second of the second o	WELLING TOU- NAPOLEON "C-ZI
Mail Section © 5.7. 4-35		Missouri
		Max. Section @ Sa. 4+85
220 CO CO CO CO CO CO CO CO CO CO CO CO CO		
220 CO CO CO CO CO CO CO CO CO CO CO CO CO		
220 CO CO CO CO CO CO CO CO CO CO CO CO CO		
220 CO CO CO CO CO CO CO CO CO CO CO CO CO		
220 CO CO CO CO CO CO CO CO CO CO CO CO CO		
220 CO CO CO CO CO CO CO CO CO CO CO CO CO		
220 CO CO CO CO CO CO CO CO CO CO CO CO CO		8
230 C C C C C C C C C C C C C C C C C C C		
200 200 200 200 200 200 200 200 200 200		
200 200 200 200 200 200 200 200 200 200		
200 200 200 200 200 200 200 200 200 200		
200 200 200 200 200 200 200 200 200 200		
200 200 200 200 200 200 200 200 200 200		
200 200 200 200 200 200 200 200 200 200		
200 Et 113 Et 11		
200 Et 113 Et 11		
200 Et 113 Et 11		
200 Et 113 Et 11		
200 Charles 100 Ch		
200 Charles 100 Ch		0
200 Charles 100 Ch		\$ \$28
200 Charles 100 Ch		
200 Charles 100 Ch	المستخصية مستهمين الماء الماء المساوية	·
200 200 2 CEM 11.3 S C		=
200 200 2 CEM 11.3 S C		
200 200 2 CEM 11.3 S C		1
250 250 250 250 250 250 250 250 250 250		
20 CE CE CE CE CE CE CE CE CE CE CE CE CE		1 1 1 2 0
20 CE CE CE CE CE CE CE CE CE CE CE CE CE		
20 CE CE CE CE CE CE CE CE CE CE CE CE CE		
20 CE CE CE CE CE CE CE CE CE CE CE CE CE		
		0/3/7
250 S		* of the 1. \ 3.10
250 252 252 252 252 252 252 252 252 252		
250 252 252 252 252 252 252 252 252 252		
		1/2 /2
		The state of the s
		2
		AND AND A DESCRIPTION OF THE PROPERTY OF THE P
	The first of the f	
		8 0 9 1
Scale: inch= Feet		N N N
		Scale: inch= => Feet

T

Ī

UNITED STATES DEPARTMENT OF AGRICULTURE SOIL CONSERVATION SERVICE

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

GENERAL

State Missouri	County Lafayette	;	50N R 23N; Watershed	lellington-Napolo	ecn
		-10 Site number C-21 S			
Investigated by Nucl	F. Edmonda, Goo.	wr-1, etc.) Equipment used <u>Hobila B-JtO</u> (Type, size, n)ate <u>6-16-66</u>	
	(Signature and title)	SITE DATA	make, Model, Sto.)		
				ilization, Sedima	
		Type of structure DI 21 n RC			
Direction of valley trend (d	ownstream)N	Maximum height of fill35.	feet . Length of	fill425	feet.
Estimated volume of comp	acted fill required				
		STORAGE ALLOCATION			
	Volume (ac. ft.)	Surface Area (acres)	Depth	at Dam (feet)	
Sediment	150	115X 16.5		29.8	
Floodwater	43.5	20.0		32.3	
					
	SURI	FACE GEOLOGY AND PHYSIC	OGRAPHY		
Physiographic description	Mo. River Loess Hi	11s Topography Rolling	Attitude of beds: Dip	Strike	
		15 percent. Width of floodplai			feet
		ed in the Missouri Rive			
		e underlying bedrock is			
•	_	is characterized as cy			
limestone and	shale.				
					
	· · · · · · · · · · · · · · · · · · ·				_

		·		*	
		 		·	_
				· · · · · · · · · · · · · · · · · · ·	
			`		

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

FEATURE Centerline of Dam, Principal Spilluay, Borrow Area

(Centerline of Dam, Principal Spillway, Emergency Spillway, the Stream Channel, Investigations for Drainage of Structure, Borrow Area, Reservoir Basin, etc.)

DRILLING PROGRAM

			Numbe	r of Samples Taken	
Equipment Used	Number	of Holes	Undisturbed	Distu	rbed
	Exploration	Sampling	(state type)	Large	Small
PA L"	6	3		4 L.Bag	
Sp.T		<u> </u>			19 Jar
Tube 3"		<u> </u>	4 Shelby		
Total	6	8	<u> </u>	4	19

SUMMARY OF FINDINGS

(include only factual data)

The abutments are deep losss classified CL below the developed soil profile. In
test hole # 2 the loess was 30 feet deep and underlain with material classified as
a stiff CH. The central section of the foundation adjacent to the channel is described a
alluvium or a modified losss and is underlain with sand classified SP and SW at depths of
35 to 40 feet. The thickness of the sandy material ranges from 3 to 6 feet. Lens of
material classified SM occurs in test holes 5 and 301. The weakest material in the found
tion is the alluxium which had a blow count of 2 from 15 to 16 feet in test hole # 301.
The foundation of the principal spillway is the alluvial material which had blow counts
ranging from 2 to 5. The alluvium is underlain with a stiff ML described as an organic
silt. SP or SW material was found at depth in all test holes on the centerline of the
principal spilluay. In test hole # 304, the SP was underlain with stiff clay classified
CH. The emergency spillway cuts are shallow and will be in the loess soil. The gully at
the conterline is active and cutting into undisturbed material. There is sufficient
borrow available within 700 feet of the centerline of the fill.

Form SCS-376C Sheet of For In Service Use Only

10-59

DETAILED GEOLOGIC INVESTIGATION OF DAM SITES

State	Missouri	Caunty	Lafay	ette		ollington- apoleon	Subwatershed			
Site n	umber C-21	_ Site group	<u> </u>	Structure class _	ь	Investigated by MUBL	F. Edmonds	Geo.	Date _6=16=0	<u> </u>

INTERPRETATIONS AND CONCLUSIONS

The abutments are deep losss and present no geologic problems. The loss below the developed soil profile has sufficient clay content to be classified (low) CL. The material in the central part of the foundation, described as alluvium, between approximate centerline stations h+CO and 5+50, is variable in texture and strength. The weakest material in test hole # 301 had a blow count of 2 and is interpreted to extend beneath the channel and to approximate centerline station 5+CO. The underlying material described as stiff organic silt extends to approximately the same distance. The alluvium in test hole # h to the right of the channel had blow counts of 6 in the upper part and ranged from 11 to 20 in the lower part. The foundation of the principal spillway is the soft to medium alluvium which extends to a depth of about 15 feet. This is underlain with a medium ML and the organic silts. The SM SP and SW material occurred consistently in all test holes through the alluvium and at a relatively uniform elevation. The SP material in test hole # 304 was underlain with a stiff clay and is assumed to underlie the sand encountered in the other test holes. Undisturbed samples of the different materials were taken in test hole # 301.

The channel is active at the centerline and to a \$ foot overfall approximately 50 feet upstream and has cut to undisturbed material. Above the overfall the channel averages 2 feet simp deep and 30 feet wide and has approximately 3 feet of soit silt and debris in the bottom. The overfall is active and could move through the foundation area before construction time. Since emergency spillway cuts are shallow and in a loss soil, it was not necessary to drill or sample.

Borrow area 103 is a loess soil and will be the best source of natorial for the core. Area 102 is high bottom or terrace alluvium and classified UL. Borrow area 101 is modern alluvium classified ML and was soft and wet below 6 feet. Estimated amounts of borrow available:

Hole No.	Cu/yas Topsoil	Cu/yds Compacted Fill
101	6000	****
102	1250	7 500
103		6000
Emergency Spillway	1250	1250
Total	8500	14,750

APPENDIX D HYDROLOGIC COMPUTATIONS

Note: Reproductions of Sheets 1 through 3 of 3 included in Appendix D are the best possible from copy furnished by Soil Conservation Service. Unreadable portions on the reproduced sheets are also unreadable on sheets from which the copies were made.

HYDROLOGIC COMPUTATIONS

- 1. The Mockes dimensionless standard curvalinear unit hydrograph and the SCS TR-20 program were used to develop the inflow hydrographs (see Plate DI). The inflow hydrograph for the 100-year flood was also generated by the consultant using the TR-20 program.
 - a. Six-hour, twelve-hour, and twenty-four hour 100-year rainfall for the dam location was taken from NOAA Technical Paper 40. The 24-hour probable maximum precipitation was taken from the curves of Hydrometeorological Report No. 33 and current Corps of Engineers and St. Louis District policy and guidance for hydraulics and hydrology.
 - b. Drainage area = 0.52 square mile; 333 acres (SCS).
 - c. Time of concentration of runoff = 20 minutes (SCS).
 - d. The antecedent storm conditions were heavy rainfall and low temperatures which occurred on the previous 5 days (SCS AMCIII). The initial pool elevation was assumed at the crest of the principal spillway.
 - e. The total 24-hour storm duration losses for the 100-year storm were 1.77 inches. The total losses for the 24-hour duration 1/2 PMF storm were 1.96 inches. The total losses for the PMF storm were 2.05 inches. These data were based on use of soils group B; pasture/range and row crop weighted to produce SCS input runoff curve No. 70 from SCS AMCII converted by TR-20 to computed curve No. 85 SCS AMCIII.
 - f. Average soil loss rates = 0.05 inch per hour approximately.
- 2. The drop inlet and conduit discharge ratings were developed using standard formulas and criteria from SCS publication design manual EWP-5 taken from Corps of Engineers publication, "Hydraulic Characteristics of Reservoir Outlet Works". The emergency spillway rating was developed using the SCS emergency spillway computer program "RESIN"; the results compared closely with data shown on the SCS as-built plans. The flows over the dam crest were based on the broad-crested weir equation $Q = CLH^{3/2}$, where H is the head on the dam crest; the coefficient C, which varies with head, was taken from the USGS publication "TWRI, Book 3, Chapter 5, Measurement of Peak Discharge at Dams by Indirect Methods" (C valued varies from 2.52 to 3.00). Sample calculations are attached.
- 3. Floods were routed through the reservoir using the TR-20 program to determine the capabilities of the spillways and dam embankment crest. The unit hydrograph computation duration interval is computed as 0.17TC by the TR-20 computer program. Copies of the input-output data from the TR-20 program used to develop the hydrographs for the PMF, 0.5 PMF, and 100-year flood are attached. The storm rainfall patterns, inflow hydrographs and routed outflow hydrographs are shown on Plate DI.

U.S. DEPARTMENT OF A CULTUME SOIL CONSERVATION SERVICE CALL OF FOOT BUSINESS MOLDER MUSEUM FACTOR FLOOD ROUTING THE ALL ALL MAN (1.734 'm ten man (1.74) (1.74) (1.74) (1.74) (1.74) (1.74) (1.74) (1.74) The property of the second sec 000 Make Since computations brite more rie algo-desistent for processes that a refer to (F & 10 const.) : 3 SIMMARY DATA E ... 0 To at tapanase and to at the state of the st 1000 81 - } - i : 7.723 the Credition for cars 计划 :1: 9 67 1 1 172223 14 to man 14 at 15 page 1 days - 14 man in the second of the second in the secon +-ilper

							eYBII/TIIDE	ŀ	PATA						:		i		
			}		-	+		1	No. of London	-	Auf humbin		17.5			-	-		
			:	. ,	; i	1 1	<u>. </u>		_					: .			+	+	
\$			- • -	_	· 1	-				i						:	i .		
					: .			. .		3		•	0.34) -		-	Ī
10 Can 10	80039	1.4	•		+	-	!		140.64	<u> </u>	many tune contracts		? ≈	•	•	•		ļ ,	
	•	<u>ः</u>		•· • •	· -	<u>.</u>	+			_	STORM DISTRIBUTION CURVE		1) =:			:		- ;-	
the minests still and	::			;	 		-	-	-	Barn House	MEDICORDAN FABRIT (MEE		7 m :		:	- :-	- - -		Ţ
THE THE PERSON THE PARTY OF THE	;			-	· - -		-	-	-	1	Taliboan		12	•			_÷	<u> </u> 	
10.1.	3		-						-		BURATION PRIN		•	٠	•		- · ·		1
8:17 18 4 17 18		÷	• •-		- -	<u> </u>	! !		i	70.81	BAISTALL COER.		برهم برهم					 	i
	ş	0,40				 -	; .		<u> </u>	2	BIRD D		4.0	••					
	, ;		! .	<u>:</u> .		-	1	-	1	10016	Todo Pain spuints		9 9		•	· :	•	•	
	5	7 30	- ! ·	:		:	+	1							:			·	Ţ
00000000000000000000000000000000000000	<u> </u>	4 A	:			-+	1	- -	i	-								•	
-	£ 3	*	:	4.		-		-	2000	15 15 15 15 15 15 15 15 15 15 15 15 15 1		200	6						
The market of the party of the terms of the court	: :	<u>۾</u> ا		. _ :	ا إ	-		- : - : 1 !	1112	==	101.		aas		• •	:		:	!
No. 5 Added and to Money, a Constant of the	A 1. 7.	l-i			1		1	· ;		4 -	SMIDDLE NA MAE.	77/11	21		•			:	I
Stor on a previous comes.	7	; + }'	: • • • •	+		! -	!		1	Ye. #14.	141.	77/116	9.	. ,	•				T
. I de ve a see persus camps			•	-		-	1		<u>[</u>	2	See 1886	WAG.	2	· · ·				•	(-
PROFESSION DATABLE OF PARTY OF THE PARTY OF	14791	1-1	. :	: <u></u>	- :-	-i -	+		BEBUCTURE	_	mitent & Prontes.		65.3						
Plan 173 Million as	Shupe	15.5	<u>.</u> .												• •			• .	
							CHANNEL	1.	HYDRAULICS	Ģ									Ţ.
7. 4.5.7			+	-	-	-	L	ı		-	-								Ī
				- ·	· ;	- 	1 !		:				· -	· ·					I
		2111	: -	• - •	•	: 	1			• •				1.			٠.	; ;	
	£	A 100.	. 4 -		+		-	-	1.	:	:							••• <u>•</u>	1
	5 1	: 1	_	- -	•••		-	! !.	• • •	; ·							. :	٠.	
3		·	•	, 	+		<u> </u>	1.		:	-			•	•			-	
	; ;	; ; ;				+-				-1.	· ·								
1,100	;	•				• :	! : I	: i	-					•			•		Γ
411 E AL QUAR 4	38.10				- :		-			-					•		,		-
ACCOUNT NOT AND ALDER	38.1	**		•	:	- ;	- !		! 			· -					•		
Trainer, B. B. Barten.	ž		•		•		-	1				•							1
# Tare 1			;		<u>:</u>	-		_ :		-		•				٠		:	
TO THE CALLETS OF A P. C. A. C. C. C. C. C. C. C. C. C. C. C. C. C.	į		- -	- :	<u> </u>	++		-	· · ·		: -	, ,			•	•		:	!
140 AAAA	į	c:	1 1	· 	1	+	11			-				•			- •		
Capitally filed has a set and	: :	7	- :	-		+	-	· 1			• •					•	Ac piin T	: <u>}</u>	i ;
Over Frome a live live 1 th Sandan and 1 th Sa	l'o		The Bilguing ribor a ribop of first-on	30 OC 11 11.00 1	10 U 180	stauctung		-									3	2	
neone Heading too property one and charges are clade buy	114														OEN	GENERAL DE	DESIGN	DATA	
" (Aunich wasnyn broad on 363.7)	194	on ses pres : Velocities besed on "1" 1's	breed	. 1.11.12.	rda ne	Alabert	bestel	D. va	Refords						ALLIERST	:5		WIERSHED PLSES	1566
•		:	1		!		1								LAPAYETTE		C XUNTY, MISSOURI	SOUR	
• .	•		:	• 1	1		:	•	• •					,	3.08	ON PEINKINGNI OF AGRICULTURE SOIL CONSCRVATION SERVICE	T OF ALK		3
		1 (i		: !		1		:							1	į	:	
	•		!				!			;	٠,	• !			1		<u>;</u>		1
								1 1						; ;	· }	:			
	1		1	1					-	- 4 '					# # # # # # # # # # # # # # # # # # #	17.00		25-25	3
		•	:		.4		Fireme.]	44.4.4	47		ار :	•	:		1		4484	1

	TR-20 ROULING.															
				0.5200 0.53100 0.75000 0.75000	22888 27888 2788 2788 2788 2788 2788 27		906.			00000000000000000000000000000000000000	555	00000000000000000000000000000000000000		000000000000000000000000000000000000000		•
				000000000000000000000000000000000000000	20020 20020	32.22 25.22 30.23		STORAGE 150.0000		000000000000000000000000000000000000000	200	000000000000000000000000000000000000000		007-50	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	•
3961 - Y 111. C	AM (SCS)		0.260	0.1800 0.4500 0.5300 0.7300	<i></i>		•	DISCHARGE U.DADO	00*18		600	0.000 000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.000 0.	MF = 0.02	224031	6.6200 6.6300 6.9300 6.9300	
1130 - DATED	NYLTTE C	1 UAM (SCS)	INCREMENT =	0.000 0.570 0.570 0.720 0.720				ELEVATION 758.0001	4= 1 VJ	0.000 0.04600 0.04600 0.04400 0.0440	0000 0000 CKERE	0.000 0.000	TINE INCREMEN	010000000000000000000000000000000000000	0.3200	JCKF PL
PROCRAM FOR 18M	INSP LAF	LAFAYLTIF C-2	VFLUCITY	0.2700 0.5700 0.5400 0.5500 0.7500	2005 2005 2005 2005 2005	926	0.6.0	•	SS HYDROGRAFH	000000000000000000000000000000000000000	1000	0.000000000000000000000000000000000000	ANLF NO. 2	000000	0.5500 0.5500 0.9500 0.9500	3
MYDROLOGY PE		DAM IRE	C TABLE	స్ పత్రి జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా జిల్లా	2225	2023 :	ENO IN	STRUCTURE IN	EUD TAL NEUS LORUE	ಸಾಖಾನಾ ಮನ್ ಮನ್ ಮನ್	FRIUTAL IMFALL T	***************************************	INFALL T	ນນນນນ	ರಿಂದ ಪ್ರಕ್ರಿಸ್ ಪ	ENOTHE T

22.6200 21.66200 22.66200 22.66200 21.66200 31.66200 31.66200	× 1 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2
00000000000000000000000000000000000000	7000 0000 0000 0000 0000 0000 0000 000
2000 2000 2000 2000 2000 21000 21000 21000 21000 21000 21000	0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
00.00000000000000000000000000000000000	16. 151CRE HEMT 0.0300 0.1800 0.1800 0.5300 0.6300 1.1000 1.9500 4.5400 7.2800 7.5100
00000000000000000000000000000000000000	110. 4 110. 6 15.00 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0
	LABL
7 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5 5	RAINFALL TABLE B B B B B B B B B B B B B B B B B B

STANDARD COLITROL INSTRUCTIONS

HYDROGRAPHS

IRCT (NI INZ OUT DATA 400, 1 DATA NO, 2 DATA NO, 3 PK H C V PH SM

1 0 0 0.348 1 1 0 1 0 0

1 6 0 7 FSR,888 0.000 0.008 1 1 1 0 0 KSLCTN STRCT 0 1

ENU OF LISTING


SULPTIN RUNOFF RESVOR ENGATA

FOLLOW	
DATA	
TABINLAR	
5	
FLUNS	
ADUL	

	*7			0 - 1 - 5 - 1			<i>יי</i> ית			• •	^	
	=1.01			100 100 100 100 100 100 100 100 100 100	.39		1.50.7	34.35 759.00	760.76	344,00	1179.43	1173.30
	Solt count	Ā		AKEA= 0.52 17.56 17.56 25.51 25.51 12.16 10.27 73.57 13.55	I= 857		AKEA= 0.52 7.3.07	2d . 36 758.83	76.0.27	245.37	1112.43 765.06	12.14.75
	HO. 2 3 SOLL	Z A ->	•	11 AINAGE 25611 AINAGE 27611 AINAGE 11 2511 AINAGE 7 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	ACKI, -1		DEALCASE AND 758,00	756,65	55.76 760.38	197,24	1029.34 763.5¢	201017
	0.25 / 1 RGH: TAME	₽¢ • Û	1 068	100 93 140 93 200 93 200 94 200 93 11	10155.07	Polits	25. 1.08 7.07	15.96	55.41 760.20	18.5.33 70.1.45	5	15, 5, 74
	CREMENT= 0 STRUCT 0	CONCENTRATIONS	CRUI OFFO	DFLTA TE B. 12. 90. 6. 12. 90. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2. 2.	S-1185= 1	LAK ELEYATIOUS	DILTA 1= 0, 78 755.03	754.35	55.06 764.03	92.197	871,24	1505.14
	IATH TAME ING ROG XSECTUVE DURATIONS	IME OF CONC	4	75, 77, 84, 70, 25, 25, 27, 25, 27, 27, 27, 27, 27, 27, 27, 27, 27, 27	25	4	75, 0.51	5.57 758.22	759.73	161,16	314.76	2607.18 705.19
	2 X X X X X X X X X X X X X X X X X X X	•	hGES 141 241 7	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 2	= 50,1946	y GES	u= 0 0 755 n1	154.17	54.00	144.35	732,26	5179,17
20000000000000000000000000000000000000		CURVE= 70	PEAK UISCHAM 237,406 244,721 3313,734 73,662 73,587	DRUGE APH T 1 05-59 206-28 206-28 240-38 3172-37 468-78 783-67 783-67	INAGE AREA	EAK DISCHARGE	PROGRAPH T.	4.55 758.15	754.32	125.82	767.76	3022.67 765.26
	ATORNA PAGEN	INPUT RUNDEF		HYD 2005-19 2006-19 2006-19 816-65 3026-39 74-12	HES ON DRA	758.00 PE	0°00 758.00	3.07 75.6.13	759.25	103.77	563.63	2079.80
ファファアシックトリック・ファック・ファック・ファック・ファック・ファック・ファック・ファック・ファ	3	STRUCTURE 0.52 IN EURVE NO.	v	1193.02 1193.02 129.02 124.02 124.03 14.03 14.03 16.03	W. IN	STRULTURE ELFVATION=	0.00 75A.00	758.11	47.19	90.36	465.21	1403.47 764.15
	IVE COLLEPOL C. IVE CONTROL C. STARTING TIF ALTER: AATE N	PUNDEF AREA= COSPUTED	PF /K TIME 11 12 13 14 15 15 15 15 15 15 15		TUTAL WATE	RESUMEACE SUMFACE PEAK TIP	<u>د</u> و	VISCHG	PISCHG	VISCHE	PLSCH6	V15CH3
N	× 201	SULROUT ITE		70042424 20042424 20042444 20046444 200464444444444		SUkPOHTINE	11PL 2.75 2.15	6.00 8.00 8.00	7.75	10.25	12.75	15.25

55.49 55.37 55.26 55.14 760.24 760.18 760.13 760.07
55.83 55.72 55.60 55.49 55.37 55.26 55.14
91,43 90.11 48,89 87.74 45.28 80.53 74.45 760.91 760.09 760.09 760.09 760.09 760.00 760.00
761.21 761.16 761.11 761.07 761.03 761.01 760.96
908.65 763.30

The component of the control of th	EXECUTIVE CONTROL STARTING TALERMATE	CONTROL I	CARD INF = 0.00 MO. = 1	CPERATIN DEP	710N COMPUT 57H= 0.50 3.2 4	. RAIN	ION XSECTN/S UURAT 1011=	1,00	KATH TABLE	U XSECTN/S NO. = 3	מור כטנוחון צמור כטנוחון	1 10:4= 3
Property Property	SUBHOU! INE		STRUCTURI	RU110F 85.0	URVE= 70	0 11	OF CONCE	NI HAT ION	•		(
Property Property		FAX 135.	s		AK UISCHAR 1629-715 34-541	ي.	J _d	CRUCIOFF)			<i>0.5</i>	-
Pervorational Pervorationa	⊢ 0€680608	00000000	40~00WW 00~00WW	SSE CONTRACTOR CONTRAC	26 55 55 55 55 55 55 55 55 55 55 55 55 55	RO= 5-5-64 103-90 1467-28 36-50 36-51 36-51 36-51	647 647 647 647 647 647 647 647 647 647	11A 1= 0 86.01 558.579 598.55 388.55 147.70	25	24024 24024 24024 26024 26024 26024 26024 26024	A 25.05.0 4.1.4.05.05.0 4.00.4.4.05.0 5.00.00.00 5.00.00 6.00	2 2 2 2 2 2 2 2 2 2 2 2 2 2 2 3 2 3
PLAN ELEVATION= Table Ta		OTAL W	TER. IN	S ON DRA	MAGE AREA	4.162		-HRS	752.1	ž	-F1= 39	2.1
FEAK_1185 FEAK_1185 FEAK_1285_1456 FEAK_1286_1456 FEAK_1285_1456 FEAK_1286_1456 FEAK_1286_1466	SUBROUTINE	PESYON SUPFACE	STRUCTURE ELEVATION=									
Figuration Fig			FES 5	14	AK 018	GES	نب	AK ELEVAT	SNOI			
0.50 PIECH 756.18 756.18 756.16 756.18 756.19 <td>5.55 5.50</td> <td>DISCHG FLEV</td> <td>58.0</td> <td>0.02 58.00</td> <td>06RAPH, T2 0.07 758.00</td> <td>0= 5.5 758.61</td> <td>758.03</td> <td>LTA T= 0 75A:06</td> <td>25 2:7</td> <td>1NAGE 4.12 58.17</td> <td>EA= 0.5 5.67 758.24</td> <td>2 7.3</td>	5.55 5.50	DISCHG FLEV	58.0	0.02 58.00	06RAPH, T2 0.07 758.00	0= 5.5 758.61	758.03	LTA T= 0 75A:06	25 2:7	1NAGE 4.12 58.17	EA= 0.5 5.67 758.24	2 7.3
0.50 PISCH6 +3.42 759.15 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 759.25 761.49 759.25 762.36 763.49 763.49 759.25 762.36 763.49 763.49 762.36 <td>9.00 0.00</td> <td>PTSC46 ELEV</td> <td>9.1</td> <td>~=</td> <td>15.2</td> <td>18.3 58.4</td> <td>21.5 5A.6</td> <td>24.7 5A.7</td> <td>28.1 58.6</td> <td>32.0 58.6</td> <td>6.9</td> <td>9.7</td>	9.00 0.00	PTSC46 ELEV	9.1	~=	15.2	18.3 58.4	21.5 5A.6	24.7 5A.7	28.1 58.6	32.0 58.6	6.9	9.7
3.00	5.5	•	43.4 59.0	59.1	9.52	49.8 59.2	200	59.2	7.1	55.1	54.5	5.3
5.50 DISCHG 800.10 1055.35 1255.31 1280.36 119.69 933.64 763.35 763.35 763.35 763.55 762.96 763.65 763.55 763.55 763.55 763.56 763.66	N N	PISCHG	55.9	M.C	28.5 61.1	83.2 61.4	47.3	61.8	77.0	62.2	88.4	93
9.00 DESCHIG 565.56 762.35 762.35 761.20 761.30 169.53 761.20 761.30 761.30 761.20 761.30 761.30 761.30 761.20 761.30 </td <td>ະ ເ</td> <td>DISCHE</td> <td></td> <td>055.9 763.5</td> <td>255.</td> <td>280.9</td> <td>19.6</td> <td>33.6</td> <td>18.5 63.1</td> <td>31.3</td> <td>62.8</td> <td>u7.5 62.հ</td>	ະ ເ	DISCHE		055.9 763.5	255.	280.9	19.6	33.6	18.5 63.1	31.3	62.8	u7.5 62.հ
0.50 PISCHG 761.01 760.96 760.91 760.76 760.80 760.76 760.76 760.80 760.76 760.70 760.66 760.60 760.	800	HISCHE	250	04.1	04.9 62.1	11.1	46.2	96.3	69.5 F1.3	47.9	30. 61.	5.0
3.00	0.00 0.00	PISCHG	02.3	95.6	9.0	7.7	3.0	80.0	76.8	73.8 60.7	.6	800
5.50 PISCHG 55.33 55.22 55.10 54.99 54.80 54.61 54.42 54.24 54.24 55.45 55.50	8.0 0.0	OFSCHG	63.09	410	3.5	5.9 5.5	5.9	55.8 60.4	55.7	5.0	5.5	5.0
#.00 DISCHG 52.94 52.44 51.74 51.15 50.56 49.99 49.42 48.21 45.17 42.8.8.00 FLEV 759.35 759.36 759.26 759.26 759.27 759.01 759.18 759.13 759.01 TOTAL WATER, IN INCHES ON DRAIMSE ARLA= 13.5221 CFS-HRS= 45.4.91 ACRE-FT= 575.01	3.5 5.5	PISCHG FLEV		55.2	5.1	6.0	9.8	54.6	± .c.	NIC.	03.	36
WATER, IN INCHES ON DRAINAGE AREA= 13.5>21 CF5-HRS= 4547.91 ACRE-FT= 575.0	5.6	DISCHG FLEV	52.9	52.4	F. W.	9.3	300	49.9 54.2	200	59.5	20	3.0
			z	S OF URA	AKEA	~,		-138	6.17.9	ACKL	-FT= 5	e.



HOSKINS-WES	TERN-SONDEREGGER
•	
CALCIU ATIONS	EAR

COMPUTED BY GG DATE 10/10/73 SHEET NO. 3 OF 3 CHECKED BY DATE JOB NUMBER 3550.

PROJECT_ Conduit Rating Contd 97 <u>5</u>2 758 C/25-Eler. 0 2 4 52 .53 53 8 759 0 2 760. a, 758.0 10 OF 12

* KINS-WESTERN-SONDEREGGER

COMPUTED BY SSU DATE 10-11-78 SHEET NO. 3 OF 3 CHECKED BY DATE JOB NUMBER 3 200

PROJECT Mo Dam Insa

TALCULATIONS FOR

Fow over Dam Embank LaFauette Co - C-21

See See		. 22 3,						26 7
	<u> </u>			المنهود ا	1 / 21 -			
		5.01	7 2 -		~~~	725	1-2-	
~	3	53/	Cam Elek					
C		7055	7/2/	2./			 	
	2 4	763.3	763.4	2. /	175	110	20/	137
+2 C	ن کــ		7111	1.4		<.15	2.70	13/
	80		764.1	7.7	1.20	-	2.87	302
1+05	70		764.5	1.0		 	2.01	302
	100		797.3	7.0	.9		2.80	239
2-00	100		764.7	. 8			2.0	
	100		797,	. 0	. 8		2.78	199
3 - c o	700		764.7	. 8		7	2.70	
	100				.85		2.79	219
4+40			764.6	. 9			4.11	
	65		/ / / /		.90		2.80	155
4-45			764.6	. 9	.,0		2.0	, 3 =
- · · · · · · · · · · · · · · · · · · ·	13				.45	,	2.67	10
4 + 78		7655	765.5	5	1,70			
	1 1				<u> </u>			
			, ; ; ;	:				1261
								
Δ		7660	763,4	2.6				
	20	7660	763,4	2.6		<.15	3.00	202
	20			2.6		<.15	3.00	202
-20	20		763,4	į i		<.15		
			764.1	į i	2.2.5 1.7	<.15	3.00 2.95	
- 2.0 . +σ.0				1.9 1.5	1.7	<.15	2.95	523
<u> - 2.0</u>	8 C		764.1	1.9	2.2.5 1.7 1.4		2.95 2.91	523 482
1 + o o	පිර		764.7	1.9 1.5 1.3	2.2.5 1.7 1.4 1.3		2.95 2.91	523 482
- 2.0 . +σ.0	8C 100 100		764.1	1.9 1.5 1.3	1.7 1.4 1.3		2.95 2.91 2.89	523 482 428
2+0 G	8C 100 100		764.1 764.5 764.7	1.9 1.5 1.3	2.2.5 1.7 1.4 1.3		2.95 2.91 2.89	523 482
1 + o o	80 100 100		764.7	1.9 1.5 1.3	2.2.5 1.7 1.4 1.3		2.95 2.91 2.89 2.90	523 482 428 455
2.+0° 2.+0° 3.+0° 4+0°	8C 100 100		764.7 764.7 764.7 764.6	1.9 1.3 1.3	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89	523 482 428
2+0 G	80 100 100 100		764.1 764.5 764.7	1.9 1.3 1.3	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313
1+00 2+00 3+00 4+00	80 100 100		764.7 764.7 764.7 764.6	1.9 1.3 1.3 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90	523 482 428 455 313
2.+0° 2.+0° 3.+0° 4+0°	80 100 100 100		764.7 764.7 764.6 764.6	1.9 1.3 1.3 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313
1+00 2+00 3+00 4+00	80 100 100 100		764.7 764.7 764.6 764.6	1.9 1.3 1.3 1.4 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313
-20 1+00 2+00 3+00 4+00 4+65 4+86	80 100 100 100		764.7 764.7 764.7 764.6	1.9 1.3 1.3 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313
2+00 2+00 3+00 4+00 4+65 4+86	80 100 100 100	766.0	764.7 764.7 764.6 764.6	1.9 1.3 1.3 1.4 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313
-20 1+00 2+00 3+00 4+00 4+65 4+86	80 100 100 100		764.7 764.7 764.6 764.6	1.9 1.3 1.3 1.4 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313
2+00 2+00 3+00 4+00 4+65 4+86	80 100 100 100	766.0	764.7 764.7 764.6 764.6	1.9 1.3 1.3 1.4 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313 34 2437
2+00 2+00 3+00 4+00 4+65 4+86	80 100 100 100	766.0	764.7 764.7 764.6 764.6	1.9 1.3 1.3 1.4 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313
2+00 2+00 3+00 4+00 4+65 4+86	80 100 100 65 21	766.0	764.7 764.7 764.6 764.6	1.9 1.3 1.3 1.4 1.4	2.2.5 1.7 1.4 1.3 1.3.5		2.95 2.91 2.89 2.90 2.91	523 482 428 455 313 34 2437

OSKINS-WEST	ERN-SONDEREGGER
CALCULATIONS	FOR

COMPUTED BY = 5- DATE	3 OF OF
CHECKED BYDATE	JOB NUMBER 8/2075
PROJECT	•

Elex H weir Cand. Em S. Embune 756.0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0		tal 2	atina	La	Fauetle-C-	-21
756,0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0				X-		3
756,0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0 0	Eler	HU	veir Cons	J. Em. S.	Embunk	Te -a
2 , 2 3,3		7				
2 , 2 3,3	758.0	0	0 3	0	1	2
	7			_		
.6 .6 .7 .8 .8 .27 .759.0 .0 .37 .2 .1.2 49 .49 .4 .4 .4 .5 .54 .6 .1.4 .5 .54 .8 .1.9 .55 .760.0 .20 .55 .55 .3760.5 .25 .56 .56 .7761.0 .30 .56 .99 .7761.5 .35 .57 .194 .7762 .40 .58 .340 .340 .7763.5 .50 .59 .744 .763.4 0 .50 .59 .744 .763.4 0 .50 .59 .744 .763.6 .56 .59 .744 .763.6 .56 .59 .744 .763.6 .56 .59 .744 .763.6 .56 .59 .744 .763.6 .56 .59 .744 .763.6 .56 .59 .744 .764.7 .67 .61 .1350 .1/ .1351 .764.7 .67 .61 .1614 .54 .1663 .764.7 .67 .61 .1760 .122 .1232 .765.5 .75 .62 .2370 .1261 .365; .766.5 .75 .62 .2370 .1261 .365; .766.5 .75 .62 .2370 .1261 .365; .766.5 .85 .64 .64				94		9.4
759.0 1.0 37 - 2 1.2 49					+	7. 7.
759.0 1.0 37 - 2 1.2 49					 	2.7
- 2 1,2 49 - 4 49 54 54 54 54 54 54 54 54 54 54 54 54 54					 	
- 4 1.4 -62 54 54 54 54 54 54 54 60 1.6 1.6 1.6 1.6 1.6 1.6 1.6 1.6 1.6 1.6		1 1 2	3/	10		16
		1 / 4		47	 	<u> 47</u>
8 1.9 55 760.0 20 55 55 5760.5 2.5 56 56 5760.7 2.7 56 73 73 7761.0 3.0 56 99 99 761.5 3.5 57 194 194 762 40 58 340 340 763 50 59 744 724 763.4 0 3 6 60 960 960 764.7 6.7 61 1350 11 1361 764.5 65 61 1614 54 1663 764.7 6.7 61 1760 122 1232 765.5 7.5 62 2370 1261 3651 765.5 7.5 62 2370 1261 3651 766.5 8.5 64 766.5 8.5 64					 	<u>\$</u>
760.0 20 55 55 55 55 55 55 55 55 55 55 55 55 55					 	
5 5.760.5 2.5 56 56 56 56 73 73 73 73 73 73 73 73 73 73 73 73 73		4 1. 3	55		 	
760,7 27 56 73 73 7761,0 30 56 99 761,5 35 57 /94 /94 762 40 58 340 340 763 50 59 744 763,4 054 crest 60 960 960 764,7 6,7 61 /350 1/ /363 764,7 6,7 61 /760 /22 /332 765,5 75 62 2370 /261 363/ 766,5 85 64 7764,0 8,0 63 2772 2437 5209 766,5 8,5 64 7767,0 9,0 64	760.0	2.0				
760,7 27 56 73 73 7761,0 30 56 99 761,5 35 57 /94 /94 762 40 58 340 340 763 50 59 744 763,4 055 crest 60 960 960 764,7 6,7 61 /350 1/ /361 764,7 6,7 61 /760 /22 /232 765,5 7,5 62 2370 /261 363/ 766,5 8,5 64 766,5 8,5 64 766,5 8,5 64 766,5 8,5 64 767,0 9,0 64	5.760.5	25	56	- 56		
761.5 3.5 57 194 194 762 40 58 340 240 763 50 59 744 723 763.4 Dan crest 60 960 960 764.1 6.1 61 1350 11 1361 764.5 6.5 61 1614 54 1663 764.7 6.7 61 1760 122 1332 765.5 7.5 62 2370 1261 3631 766.5 8.5 64	-760,7	1 2.7				7.3
761.5 3.5 57 194 194 762 40 58 340 240 763 50 59 744 723 763.4 Dan crest 60 960 960 764.1 61 61 1350 11 1361 764.5 6.5 61 1614 54 1663 764.7 6.7 61 1760 122 1232 765.5 7.5 62 2370 1261 3631 766.5 8.5 64	7761,0	3.0	56			9
$\begin{array}{c ccccccccccccccccccccccccccccccccccc$	-761.5	3.5	57	194		194
763.656 56 60 764.161 61 1350 11 1361 764.565 61 1614 54 1663 764.767 61 1760 122 1232 1765.070 62 1979 340 2319 765.575 62 2370 1261 3631 1766.585 1766.585 1767.090 1764	7762	40	58	340		340
763.656 56 60 764.161 61 1350 11 1361 764.565 61 1614 54 1663 764.767 61 1760 122 1232 1765.070 62 1979 340 2319 765.575 62 2370 1261 3631 1766.585 1766.585 1767.090 1764	~763	5.0	59	744		724
763,656 764:161 61 1350 11 1361 764:565 61 1614 54 1663 764:767 61 1760 122 1332 765.07.0 62 1979 340 2319 765.575 62 2370 1261 3631 766.585 64 -767.090	763.4	- Danger	est 60	960		960
764.5 65 61 1350 11 1361 764.5 65 61 1614 54 1663 764.7 6.7 61 1760 122 1352 -765.0 7.0 62 1979 340 2319 765.5 75 62 2370 1261 3631 -766.0 8.0 63 2772 2437 5209 766.5 8.5 64	743.6	5.6	60			
764.5 65 61 1614 54 1663 764.7 6.7 61 1760 122 1352 -765.0 7.0 62 1979 340 2319 765.5 7.5 62 2370 1261 3631 -766.0 8.0 63 2772 2437 5209 -767.0 9.0 64		11 6 1		1350	1/	1361
-765.0 7.0 62 1979 340 2319 765.5 75 62 2370 1261 365; -766.0 8.0 63 2772 2437 5209 -767.0 9.0 64		7 (5				1663
-765.0 7.0 62 1979 340 2319 765.5 75 62 2370 1261 365; -766.0 8.0 63 2772 2437 5209 -767.0 9.0 64	764.7	1 6 7				1292
765.5 7.5 62 2370 1261 3631 -766.0 8.0 63 2772 2437 5209 766.5 8.5 64 -767.0 9.0 64	-705.0			1979	240	7 2 1 3
-766.0 8.0 63 2772 2437 5209 -766.5 8.5 64 -767.0 9.0 64	765.5	7 7 5				
-767.0 9.0 64		80	63	2772		
-767.0 9.0 64		1 2 3			 	5_5
769.0 7	- 760.7	9.0			 	
	767.0	1/0			 - 	
		7 7 9	63	- 	 	
		1		 	 - 	
╶┍╃╬╫╫╫╇╇╫╫╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇╇	-+++++	1			 	
┍┈┊╶┊╶┊╶┊╶┊╶┋╶┋╶┋╶┋ ╌┩ ╒┩╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇╒╇						
╼╴ ┊╸┊┈╒╶┊┈╒╶┋┈┊┈┆┈┆┈┆┈┆┈┆┈┆┈┆┈┆┈┆┈┆┈┆┈			+ + + + + + + + + + + + + + + + + + + +		 	
					7 7 0 6	
X-Includes P.S. Flow			+ + + + + + + + + + + + + + + + + + + +	ALAC	JUOKS P.S	s. 1-10w
			 			
From Comp. Run			+ + + +	(170	m comp.	eun)
					+	
-					+ + + + + + + + + + + + + + + + + + + +	- 1 · 1 · 1 · 1 · 1 · 1 · 1 · 1 · 1 · 1
	. 					
	:	- 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1			+	
						
				<u> </u>		12.0F12
				 		

